CERTIFICATE OF COMPLIANCE

Certificate Number 20160302-E302981

Report Reference E302981-20060213

Issue Date 2016-MARCH-02

Issued to: BARKSDALE INC

3211 FRUITLAND AVE LOS ANGELES CA 90058

This is to certify that representative samples of

POWER CIRCUIT AND MOTOR-MOUNTED APPARATUS

See addendum page

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: Standard for Industrial Control equipment, UL508

Industrial Control Equipment, CSA C22.2 No. 14-13

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC





CERTIFICATE OF COMPLIANCE

Certificate Number 20160302-E302981

Report Reference E302981-20060213

Issue Date 2016-MARCH-02

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL, CNL: Pressure Transducer, Model 423, followed by H3, H3-E, H5, H5-E, H6, H6-E, T4, T4-E, T5, T5-E, T8, or T8-E, followed by -01, -21, -03, -22, -04, -05, -06, -07, -09, -19, -10, -12, -13, -14, -15, -16, -17, or -18, may be followed by -Z10, -Z11, -Z12, -Z15, -WXX, or -4 digits, may be followed by P1 - P10, or Q1-Q99, or -S, and -U.

Pressure Transducer, Model 425, followed by H3, H3-E, H5, H5-E, H6, H6-E, T4, T4-E, T5, T5-E, T8, or T8-E, followed by -23, -25, -01, -21, -22, -03, -04, -05, -06, -07, -08, -19, -10, -11, -12, -13, -14, -15, -16, -17, and -18, may be followed by -Z10, -Z11, -212, -Z15, -WXX, or -4 digits, may be followed by P1 - P10, or Q1-Q99, or -S, and -U.

Pressure Transducer, Model 426, followed by H3, H3-E, H5, H5-E, H6, H6-E, T4, T4-E, T5, T5-E, T8, or T8-E, followed by -23, -25, -01, -21, -03, -22, -04, -05, -06, -07, -08, -19, -10, -11, -12, -13, -14, -15, -16, -17, and -18, may be followed by -Z10, -Z11, -Z12, -Z15, -WXX, or -4 digits, may be followed by P1 - P10, or Q1-Q99, or -S, and -U.

Pressure Transducer, Model 420, followed by H3, H3-E, H5, H5-E, H6, H6-E, T4, T4-E, T5, T5-E, T8, or T8-E, followed by -01, -03, -04, -05, -06, -07, -08, -10, -11, -12, -13, -14, -15, -17, and -18, may be followed by -Z10, -Z11, -Z12, -Z15, -WXX, or - 4 digits, may be followed by P1 - P10, or Q1-Q99, or -S, and -U.

Pressure Transducer, Model 422, followed by H3, H3-E, H5, H5-E, H6, H6-E, T4, T4-E, T5, T5-E, T8, or T8-E, followed by –25, -21, -22, -01, -03, -04, -05, -06, -07, -08, -10, -11, -12, -13, -14, -15, -17, and -18, may be followed by -Z10, -Z11, -Z12, -Z15, -WXX, or – 4 digits, may be followed by P1 - P10, or Q1-Q99, or –S, and -U.



Bruce Mahrenholz, Director North American Certification Program

UL LLC



